


Deepwater Horizon (MC-252) - Situation Status Map

5/10/2010 0600 Hrs




Overflight Observations

→ Flight Path

- A - Silver Sheen w/ Potential Algae Bloom
- O - Orange Emulsified Oil
- DB - Dull Brown Oil
- TS - Transparent Sheen
- 1 - Western Edge of Source Patch
- 2 - Source Patch mostly 20% Silver Sheen with some Dull Brown Oil
- 3 - Brown and Orange Oil w/ Silver and Rainbow Sheen

Source: Chandeleur Islands flight from 1000-1500 hrs 05-09-2010.
Spill site flight from 1400-1550 hrs 05-09-2010.

Source: Forecast derived from NOAA forecast trajectory for 1800 CDT on 5-10-2010, 5-11-10 and 5-12-10.
Potential oiling extent derived from remote sensing assessment based on national and commercial sources, 1300 CDT on 5-9-2010.



- Incident Location
- Unified Area Command
- Incident Command Post
- Staging Area
- Vessel Port
- Oil Slick Extent

For Official Use Only

